

RAB PEKERJAAN PERBAIKAN KEBOCORAN FOOT VALVE POMPA NO.1
LOKASI : BOOSTER PUMP SEI AGUL

No	Uraian Pekerjaan	Ukuran Ø	Volume	Satuan	Analisa	Harga Satuan (Rp)	Jumlah Harga (Rp)
I	BOOSTER PUMP SEI AGUL						
	<u>Material</u>						
1	Foot Valve Mizu 250mm	250 mm	1,0	bh	Hitung	Stok Gudang	Stok Gudang
3	Rubber Packing T= 5 mm	-	1,00	mtr	Tabel	220.000	220.000
						Total I	220.000
	<u>Biaya Pelaksanaan</u>						
1	Bongkar pasang Spool Piece	250 mm	1,00	set	Tabel	721.000	721.000
2	Bongkar pasang foot valve	250 mm	1,00	bh	Tabel	721.000	721.000
						Total II	1.442.000
						Grand Total	1.662.000,00
						Dibulatkan	1.662.000,00

Terbilang :
Satu Juta Enam Ratus Enam Puluh Dua Ribu Rupiah

Disyahkan Oleh,

Ali Ismail Siregar

Kadiv.Perencanaan Air Minum

Diketahui Oleh,

Dedi Gusman

Kadiv.Transmisi Distribusi

Medan, April 2024

Dihitung oleh,


Julfan Fadhlil
 Kabid. Operasional Pompa